

AVIC U-Series Firmware Update Change History

Applicable models: AVIC-U310BT

Ver 1.0003

CHANGE HISTORY:

- Fixes the case where system may not pair with some Bluetooth enabled mobile phones when optional POI data SD Card is inserted into system
- Improves the reliability of touch panel when touch panel is removed and replaced before turning car on or off
- Fixes the case where contact information does not transfer from Bluetooth enabled mobile phone to system when any contact information contains an apostrophe symbol
- Fixes the case with AVIC FEEDS where data from Fuel Report cannot be read by AVIC FEEDS